

CWX Compact Cutoff Wall Pack


INSTALLATION/INSTALACIÓN

Disconnect the power before installation. Exploded view of completed assembly with component call out. 1, 2, 3, etc.

Desconecte la alimentación antes de la instalación. Vista de despiece del conjunto completo con indicación de componentes. 1, 2, 3, etc Débranchez l'alimentation avant l'installation. Vue en éclaté de l'assemblage complet, avec le nom des composants. 1, 2, 3, etc.

Sensor Installation - Z10 Part B 1 Unscrew the two M5*12 screws. remove the knockout cover. Part A Place Part A perpendicular to Part B M5*12 screws and remove Part A in the direction of the arrow. Separate A from B. Adjust wattage and CCT according to your requirement (The default setting: CCT - 5000K; Wattage - 40W). 2 Drill the Φ21mm hole. Insert Z10 base to the left hole. Z10 Base Z10 Base Mount Bracket 3 Waterproof Nut Tighten Z10 base with mount bracket and waterproof nut. 4 Z10 receptacle Connect wires according to the left wiring diagram. White N LED Driver LED Fixture G^{Yellow/Gree} 5 Align the hole and lock Z10 sensor.

CWX Compact Cutoff Wall Pack



CWX Compact Cutoff Wall Pack

